


BB 'Left,Down,In': Left 20mm, Down 20mm, In 60mm


WL G=0, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=21.14, in=-61.51, up=-20.04; Gantry tilt=0, Gantry sag=0.dcm

CAX to BB: 1.68mm




WL G=90, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=21.99, in=-61.25, up=-19.18; Gantry tilt=0, Gantry sag=0.dcm

CAX to BB: 2.15mm



WL G=180, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=20.86, in=-58.87, up=-19.93; Gantry tilt=0, Gantry sag=0.dcm

CAX to BB: 0.34mm



WL G=270, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=18.27, in=-58.56, up=-19.80; Gantry tilt=0, Gantry sag=0.dcm

CAX to BB: 3.01mm

